AerMonitor AM-1015 for WinXP

There are two steps to do:

1. **Flash PIXCIR for WinXP**
2. **Install PIXCIR HID driver**

Unzip "XP-Touch Driver and Calibration.zip"

## 1. Flash PIXCIR for WinXP

HID_Download_V2.7.exe
DynLED MFC Application

Run HID_Download_V2.7.exe

select "Setting" Button and remember the Version "0x1107"
select "Switch to COM"

Found New Hardware Wizard

Welcome to the Found New Hardware Wizard

Windows will search for current and updated software by looking on your computer, on the hardware installation CD, or on the Windows Update Web site (with your permission).

Read our privacy policy

Can Windows connect to Windows Update to search for software?

○ Yes, this time only
○ Yes, now and every time I connect a device
● No, not this time

Click Next to continue.

[< Back] [Next >] [Cancel]

Found New Hardware Wizard

This wizard helps you install software for:

Touch

If your hardware came with an installation CD or floppy disk, insert it now.

What do you want the wizard to do?

○ Install the software automatically (Recommended)
● Install from a list or specific location (Advanced)

Click Next to continue.

[< Back] [Next >] [Cancel]

select path, where "manbo_driver.inf" is lacated
"C:¥Documents and Settings¥Administrator¥My Documents¥XP-Touch Driver and Callibration¥XP-Touch Driver and Callibration"

Found New Hardware Wizard

Please choose your search and installation options.

○ Search for the best driver in these locations.

Use the check boxes below to limit or expand the default search, which includes local paths and removable media. The best driver found will be installed.

☐ Search removable media (floppy, CD-ROM...)

☑ Include this location in the search:

iver and Callibration\XP-Touch Driver and Callibration   [Browse]

○ Don't search. I will choose the driver to install.

Choose this option to select the device driver from a list. Windows does not guarantee that the driver you choose will be the best match for your hardware.

[< Back] [Next >] [Cancel]

Hardware Installation

⚠ The software you are installing for this hardware:

Pixcir TouchPanel Virtual COM Device

has not passed Windows Logo testing to verify its compatibility with Windows XP. (Tell me why this testing is important.)

Continuing your installation of this software may impair or destabilize the correct operation of your system either immediately or in the future. Microsoft strongly recommends that you stop this installation now and contact the hardware vendor for software that has passed Windows Logo testing.

[Continue Anyway] [STOP Installation]

When finish, go ahead below.


select **EEPROM Pixcir File** "OPEN"

select: "AUO_15inch_20120403_3mm_Firich_code_out.eep.pix"

select **EEPROM Pixcir File** "DOWNLOAD"

select: "SWITCH TO HID"

Clean your Touch Glass an select "Calibrate"

Close "PIXCIR Control Deskwork" and install the PIXCIR HID Driver

2. Install PIXCIR HID Driver

setup.exe
Setup Application

Run setup.exe

pixcir Setup

User Information
Enter your user information and click Next to continue.

Name:

POS

Company:

Novopos AG

[< Back] [Next >] [Cancel]

pixcir Setup

### Installation Folder
Where would you like pixcir to be installed?

The software will be installed in the folder listed below. To select a different location, either type in a new path, or click Change to browse for an existing folder.

Install pixcir to:

C:\Program Files\pixcir   [Change...]

Space required: 86.5 KB

Space available on selected drive: 54.30 GB

[< Back] [Next >] [Cancel]

pixcir Setup

Shortcut Folder
Where would you like the shortcuts to be installed?

The shortcut icons will be created in the folder indicated below. If you don't want to use the default folder, you can either type a new name, or select an existing folder from the list.

Shortcut Folder:

pixcir

(•) Install shortcuts for current user only
( ) Make shortcuts available to all users

[< Back] [Next >] [Cancel]

---

pixcir Setup

Ready to Install
You are now ready to install pixcir 1.3

The installer now has enough information to install pixcir on your computer.

The following settings will be used:

Install folder: C:\Program Files\pixcir

Shortcut folder: pixcir

Please click Next to proceed with the installation.

[< Back] [Next >] [Cancel]

pixcir Setup

Installation Successful

The pixcir 1.3 installation is complete.

Thank you for choosing pixcir!

Please click Finish to exit this installer.

[< Back] [Finish] [Cancel]

Hardware Installation

⚠ The software you are installing for this hardware:

Pixcir touch screen

has not passed Windows Logo testing to verify its compatibility with Windows XP. (Tell me why this testing is important.)

Continuing your installation of this software may impair or destabilize the correct operation of your system either immediately or in the future. Microsoft strongly recommends that you stop this installation now and contact the hardware vendor for software that has passed Windows Logo testing.

[Continue Anyway] [STOP Installation]

Pixcir Driver Install Progress

Pixcir Driver Install Successful!

[OK]

Check your device manager

Close Windows and reboot

3.12.2012 Fe

Novopos AG