

XP-3685: BIOS-UD to C09A

Check whether the BIOS is C09A.
C09A only supports TPM.

If the BIOS is C09, please update to **C09A**


Download the Utility with the BIOS C09A.

https://www.novopos.ch/client/FEC-Firich/X-POS/Driver-Package/WIN_C09A.zip

The C09A BIOS will update the ME.

So before updating the BIOS, you must first enter the BIOS to disable the ME option under advanced, save and exit.

Change the option in the figure below to Disable



Run in Windows "**FlashBios.cmd**"

Do not interrupt the flash process.

It takes about a few minutes, the system will reboot after

23.12.2021 fe
NOVOPOS AG