

Touch FW update SOP

1. Run “eGalaxUpdate”

Name	Date modified
79ff	9/3/2015 3:57 PM
1185_B100	9/3/2015 3:57 PM
CustomerSetting	8/12/2013 4:44 PM
Declaration and Disclaimer	2/10/2012 6:41 PM
eGalax5960Suite	7/31/2015 10:16 AM
eGalaxCalibration	7/1/2015 3:56 PM
eGalaxCalibration	11/13/2012 10:18 ...
eGalaxFPCTester	7/31/2015 10:15 AM
eGalaxFPCTester	8/29/2014 4:06 PM
eGalaxRawTuner	7/31/2015 10:17 AM
eGalaxRawTuner	1/23/2014 1:54 PM
eGalaxSensorTester	7/31/2015 10:14 AM
eGalaxTuner5960_Release	7/31/2015 10:16 AM
eGalaxUpdate	7/31/2015 10:12 AM
eGalaxUpdate	8/27/2014 4:11 PM
EULA.pdf	10/28/2014 9:55 AM
HIDdAPI.dll	7/31/2015 10:11 AM
LastTestLog	9/3/2015 3:59 PM
OPDraw User Guide.pdf	11/1/2012 11:50 AM
OPDraw	7/31/2015 10:13 AM
OPDraw_5960	3/24/2015 12:01 PM
PCAP7910_LD1185_B100_V00_T15_auo_15p_Dthqa.791p	9/3/2015 3:49 PM
SensorTest_Result	9/3/2015 3:59 PM
UniformityTableResult	9/3/2015 3:58 PM
version	4/14/2015 3:50 PM

2. Click “Load image”

eGalaxUpdate v2.3.5.2 For AUO-Demo (EXC7910)

Update

Current Controller		Target Firmware	
FW Update	Enable	Type	-
Loader Version	0 0	Model	-
Type	PCAP7910 SERIES	Version	-
Model	DIPPER_1185	Interface	-
Version	00_T13	Support Touch	-
Interface	Combo	CRC	-
Support Touch	10	Parameter Version	-
CRC	0x079C	Parameter CRC	-
Parameter Version	00.00		
Parameter CRC	0xAE9E		

Load Image

Image Name

Erase : 0 %


Download : 0 %

Go!


Device installed.

Apply


3. Click image “PCAP7910_LD1185_B100_V00_T15_auo_15p_Dthqa.791p” and then click “Open”



4. Click “Go!”



5. Finish and click "OK"



6. F/W update to T15

