



(RS232 Interface)

How TO Upload Logo Image And Print Logo


On The PS3100 SOP

1-1 Please entry (A) folder path

1-2 Please execute (B) printer test AP




2. Please select File→Open→Rs232 Com port




3. Please select A.Rs232 Com Port”Com1, B Brg Set ”115200”, C Hardshake “None”.

3-1 Please click “Start” icon.



4. Please select “Image Function”→ “NV Bit Image Define”


And then select logo image file to upload Logo image to CGROM



5. Logo upload successfully.




6. You are able to upload second logo to CG ROM



7. Please select “Image Function”→ “NV Bit Image Print”
→”NV1”→”Normal mode printing” for print out NV1 logo

Note: If you want to print out NV2 logo, please select “NV2”→”Normal mode printing for print out NV2 logo.”



8. Print out logo successfully.

